

Inspection Photos

2/13/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335966

Inspection Doc: 696205608

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO


**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335966



February 13, 2024



February 13, 2024

Photo 1: Photos taken from the Location entrance, facing east and south. Photos provide an overview of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335966



Photo 2: Photos examples showing areas of the Location under the “Chevron O06 696 443338, Land Application Site”.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335966



Photo 3: Wells on Location.