

Final Reclamation and Stormwater Inspection

Date: 02/20/2024

Operator: NOBLE ENERGY INC - 100322

Location ID: 332925

Inspection Document #: 708200928

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 1. Facing northeast. It appears the Operator has performed final reclamation activities with some desirable perennial vegetation observed throughout. There was also the presence of some undesirable vegetation (e.g. kochia) observed throughout the reclaimed areas and it appears that the location was recently mowed in order to manage undesirable species. Therefore, this location will remain in process until it can be inspected during the active growing season.

Inspection Photos
Location Name: Samuel J 65N66W
Location ID: 332925



Photo 2. Facing east from the northwest corner. See comments in Photo 1.

Inspection Photos
Location Name: Samuel J 65N66W
Location ID: 332925



Photo 3. Facing southwest from the northeast corner. See comments in Photo 1.

Inspection Photos
Location Name: Samuel J 65N66W
Location ID: 332925



Photo 4. Facing northwest from the southeast corner. See comments in Photo 1.

Inspection Photos
Location Name: Samuel J 65N66W
Location ID: 332925



Photo 5. Facing east along the former access road, which has been paved over and is currently a trail.

Inspection Photos
Location Name: Samuel J 65N66W
Location ID: 332925



Photo 6. Old location sign observed in the northwest corner of the location. Yellow barricade appears to be in use for a municipal stormwater/sewer cover.