

Inspection Photos

2/13/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335722

Inspection Doc: 696205614

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335722



February 13, 2024



February 13, 2024

Photo 1: Photos taken from the south end of the Location, facing northwest and northeast. Photo provides an overview of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335722



Photo 2: Line at produced water tank missing cap/plug.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335722




Photo 3: Signage not observed at the tank battery facility; signage missing, or not conspicuously posted at the battery facility.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335722



Photo 4: Wildlife protection BMPs missing from the methanol tank containment measure.