

Inspection Photos

2/13/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335729

Inspection Doc: 696205616

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335729



Photo 1: Photos 1-2 taken from the north end of the Location. Photos provides an overview of the Location from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335729



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335729



Photo 3: Signage not observed at the tank battery facility; signage missing, or not conspicuously posted at the battery facility.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335729



February 13, 2024

Photo 4: Tears observed in liner at the tank battery facility containment BMP.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources