

Inspection Photos

2/13/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335716

Inspection Doc: 696205618

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335716



February 13, 2024

Photo 1: Photo taken from the location entrance, facing northeast. Photo provides an overview of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335716



Photo 2: Signage installed at the battery facility.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335716



Photo 3: Netting installed to prevent wildlife access to the secondary containment measures.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335716




Photo 4: Photo left copied from the 10/9/2023 inspection report. Photo right shows signage at the partially buried tank remains illegible.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources