

Inspection Photos

2/13/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335709

Inspection Doc: 696205621

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335709



Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335709



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335709



Photo 3: Photo shows signage at the tank battery facility is missing, or not conspicuously posted at the facility.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335709



Photo 4: Photo left example showing signage with Operator information, including the emergency number is missing. NFPA Label has also faded. Photo right shows line at tank missing required cap/plug.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335709



Photo 5: Photo shows unused fence panels stored at wells.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources