

Inspection Photos

2/13/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335998

Inspection Doc: 696205624

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335998



Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335998



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335998



Photo 3: Wildlife protection BMPs missing or insufficient at the methanol tank containment BMP.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335998



February 13, 2024

Photo 4: Photo shows partially buried tank at the battery facility. Tank has been covered with snow; label information not legible. Containment BMP has also filled with snow. Maintenance advised.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources