

Operator: CIVITAS NORTH LLC
Location Name: Hunt 8-60 17B
Loc ID: 457475
Inspection: 696305980



Exhibit A



Exhibit B

CA: 24 Hour Emergency Number on Wellhead Sign does not reflect Current Operator. Install sign to comply with Rule 605.d.

CA Resolution: Operator has made the appropriate updates to the Wellhead sign to comply with Rule 605.d.



Exhibit A

CA: Panels - Fencing is in disrepair - see photos. Comply with Rule 606.

CA Resolution: Operator has repaired/properly installed fencing to comply with Rules 606 and 603.h.