

Inspection Photos  
Location: Red Rocks 35-11  
Facility ID: 484360



**Photo 7 – Drill Cuttings not properly stored**



**Photo 8 – Drill cuttings in native pasture**