

# Interim and Stormwater Inspection

February 15, 2023

Operator: PDC Energy - #69175

Location ID: 446251

Inspection Document #: 709400795

Weld County, CO

SWSW Section 27 T1N R66W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Rael 34-4-2HC  
Facility ID: 446251



**Photo 1.** Photo taken of location sign.



**Photo 2.** Photo taken of wellheads on site. Photo taken facing southwest.





Inspection Photos  
Location Name: Rael 34-4-2HC  
Facility ID: 446251



**Photo 3.** Photo taken of vegetation and weeds (russian thistle) in interim reclaimed area of well pad. Photo taken facing west.



**Photo 4.** Photo taken of vegetation and weeds (russian thistle) in interim reclaimed area of well pad. Photo taken facing northwest.



Inspection Photos  
Location Name: Rael 34-4-2HC  
Facility ID: 446251



**Photo 5.** Photo taken of tank battery on site. Photo taken facing northeast.



**Photo 6.** Photo of tank battery sign.



Inspection Photos  
Location Name: Rael 34-4-2HC  
Facility ID: 446251



**Photo 7.** Photo of trash on northwest corner of pad. Photo tank facing east.



**Photo 8.** Photo of weeds (russian thistle & cheatgrass) on the north side of pad. Photo taken facing north.





Inspection Photos  
Location Name: Rael 34-4-2HC  
Facility ID: 446251



**Photo 9.** Photo of vegetation and weeds (cheatgrass) on north side of tank battery pad. Photo tank facing east.



**Photo 10.** Photo of topsoil stockpile and topsoil to be salvaged. Photo tank facing south.





Inspection Photos  
Location Name: Rael 34-4-2HC  
Facility ID: 446251



**Photo 11.** Photo of weeds (russian thistle) and unstabilized soil on the northeast side of pad. Photo taken facing west.



**Photo 12.** Photo of weeds (russian thistle) on east side of pad. Photo taken facing south.

