

Inspection Photos

API: 011-06126

Operator: STRACHAN EXPLORATION INC

Inspection Date: 2/21/2024

County: Bent



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south toward the location. The sign posted at meter shed is faded and not legible. Previous CA was not completed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. Facing toward the tank battery. There is insufficient secondary containment to contain a spill. Previous CA was not completed.

