

Final Reclamation Inspection

February 22nd, 2024

Operator: Simcoe LLC - 10749

Location ID: 326680

Inspection Document #: 714000464

La Plata County, CO

Township: SENW 8 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Clovis B 2
Location ID: 326680

2/22/24
+37.121429,-107.849827
333° NW



Photo 1. View of the disturbance facing center from the entrance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08680

Inspection Photos
Location Name: Clovis B 2
Location ID: 326680

2/22/24
+37.121429,-107.849827
19° N



Photo 2. View of eastern interim reclamation facing north.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08680

Inspection Photos
Location Name: Clovis B 2
Location ID: 326680



Photo 3. Weedy debris CA from previous inspection doc #693902981 has been addressed/resolved.

Inspection Photos
Location Name: Clovis B 2
Location ID: 326680



Photo 4. View of produced water sign that is illegible.



Inspection Photos
Location Name: Clovis B 2
Location ID: 326680



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of surface owner trailers stored on the northern edge of the disturbance.

API #: 067-08680

Inspection Photos
Location Name: Clovis B 2
Location ID: 326680

2/22/24
+37.119353,-107.847904
149° SE

