

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 2/22/2024



Location Entrance – Photo #09441



Wellheads – Photo #09442

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 2/22/2024



Separators – Photo #09444



Tank Battery – Photo #09446

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 2/22/2024



Open-Ended Load Line – Photo #09449



Open-Ended Load Line – Photo #09451

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 2/22/2024



Open-Ended Load Line – Photo #09453



Open-Ended Load Line – Photo #09455

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 2/22/2024



Rill Erosion from Location onto Lease Road – Photo #09456

