

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 23-27

Location ID: 335425

Date: 2/22/2024



Wellheads – Photo #09470



Separators – Photo #09474

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 23-27

Location ID: 335425

Date: 2/22/2024



Heater Treaters – Photo #09476



Tank Battery – Photo #09477

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 23-27

Location ID: 335425

Date: 2/22/2024



Lack of Stabilization – Photo #09472



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09473**