

**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC PA 311-34 Pad**  
**Location ID: 335337**



**Location Overview: Location is within High Priority/Density  
Habitat areas & in close proximity to NSO/Black Bear Habitat  
areas. Location is within Rule 411a Surface Water  
Intermediate Buffer.**

**Section/Township/Range: 34 6S95W**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC PA 311-34 Pad**  
**Location ID: 335337**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC PA 311-34 Pad**  
**Location ID: 335337**



**Photo # 7168 Check dam needs maintenance**



**Photo # 7169 Check dam needs maintenance**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC PA 311-34 Pad**  
**Location ID: 335337**



Feb 21, 2024 at 1:34:13 PM  
CO

**Photo # 7170 Check dam needs maintenance**



Feb 21, 2024 at 1:35:19 PM  
CO

**Photo # 7171 Erosion & transport of sediment off location & into the interim area/insufficient BMP's/run off controls.**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC PA 311-34 Pad**  
**Location ID: 335337**



**Photo # 7172 Erosion & transport of sediment off location & into the interim area/insufficient BMP's/run off controls.**



**Photo # 7173 Erosion & transport of sediment off location & into the interim area/insufficient BMP's/run off controls.**