

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWNE

Location ID: 335459

Date: 2/22/2024



Location Entrance – Photo #09484



Wellheads – Photo #09485

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWNE

Location ID: 335459

Date: 2/22/2024



Separators – Photo #09486



Tank Battery – Photo #09487

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWNE

Location ID: 335459

Date: 2/22/2024



Tank Not Labeled – Photo #09490



Open-Ended Load Line – Photo #09488

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWNE

Location ID: 335459

Date: 2/22/2024



Open-Ended Load Line – Photo #09491