

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/14/2024

Submitted Date:

02/19/2024

Document Number:

709100231**FIELD INSPECTION FORM**Loc ID 303344 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 25255Name of Operator: DUKE GAS COMPANY LLCAddress: 22500 COUNTY RD 24City: VERNON State: CO Zip: 80755**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kyle Waggoner		kyle.waggoner@state.co.us	
Cantrall, Diana		djcantrall@gmail.com	
Krystal Heibel		krystal.heibel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
303344	LOCATION	AC			-	ARCO-STATE-61S45W 16SESW	EI

General Comment:

On Feb 14, 2024, ECMC Environmental Unit Staff Krystal Heibel inspected the Arco-State 16-4 location (Location ID: 303344).

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location					
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment:					
Corrective Action:				Date: _____	
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:				corrective date	
Type:	#				
Comment:		The Arco-State pit (Facility ID 101939) is active on-site, but tied to no wells. Fluid within in pit is likely due to recent rainfall event.			
Corrective Action:		Operator shall submit a Form 27 Site Investigation and Remediation Workplan to decommission the pit. Further site investigation is needed. Operator shall conduct a closure investigation in accordance with Rule 911.c. Pit Closure Guidance Document. Operator shall collect confirmation soil samples as described in the Rule 915.e.(2) Guidance Document. Operator will analyze soil samples for TPH (C6-C36), Table 915-1 Organic Compounds in Soil, Table 915-1 metals, and Table 915-1 Soil Suitability for Reclamation (Electrical conductivity, Sodium adsorption ratio, and pH by saturated paste method, boron (hot water soluble)).		Date: 03/20/2024	
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	303344	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403691866	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6434663
709100232	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6434654