

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/21/2024

Submitted Date:

02/26/2024

Document Number:

697602272**FIELD INSPECTION FORM**Loc ID 332553 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 2001 16TH STREET SUITE 900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------------------------------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | ALL INSPECTIONS |
| , | | rbucogccinspectionreports@c hevron.onmicrosoft.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|---------------------|--------|-------------|------------|-----------|---------------------------------|-------------|
| 247708 | WELL | TA | 03/24/2022 | GW | 123-15505 | HSR-DECKER 8-26 | EI |
| 289446 | WELL | PA | 12/11/2014 | GW | 123-24847 | SCHMIDT 24-26 | EI |
| 485725 | SPILL OR RELEASE | CL | 12/07/2023 | | - | HSR-Decker 8-26 Tank Battery | EI |

General Comment:

ECMC environmental inspection to determine progress at Facility ID 332553. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

| Location | | | | |
|--|------|--------|-------|--|
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Emergency Contact Number: | | | | |
| Comment: <input type="text" value="Good"/> | | | | |
| Corrective Action: <input type="text"/> | | | | |
| Date: <input type="text"/> | | | | |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: <input type="text"/> | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Venting: | | | | |
| Yes/No | | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Flaring: | | | | |
| Type | | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|----------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 247708 | Type: | WELL | API Number: | 123-15505 | Status: | TA | Insp. Status: | EI |
| Facility ID: | 289446 | Type: | WELL | API Number: | 123-24847 | Status: | PA | Insp. Status: | EI |
| Facility ID: | 485725 | Type: | SPILL OR | API Number: | - | Status: | CL | Insp. Status: | EI |

| Environmental | | |
|--------------------------------------|--|-------------|
| Spill/Remediation: | | |
| Comment: | Historical release near the Produced Water Vessel. Most equipment has been removed from the location except for the meter house. Excavations have been backfilled. Monitoring wells have been installed. | |
| Corrective Action: | | Date: _____ |
| Emission Control Burner (ECB): _____ | | |
| Comment: | | |
| Pilot: _____ | Wildlife Protection Devices (fired vessels): _____ | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 697602273 | Photolog | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6443210 |