

Operator: CIVITAS NORTH LLC
Location Name: Hunt 8-60 17A
Loc ID: 457131
Inspection: 696305979



Exhibit A

CA: Day Tanks - Wildlife Netting is in disrepair. Deceased birds and Debris is present; See Photos. Secondary Containment with Chemical Drums inside - Wildlife Netting is MISSING; See Photos. Comply with Rule 606. Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b

CA Resolution: Operator has appropriately repaired/installed Wildlife Netting at identified areas of location to comply with Rule 902.b. Covering and appropriate cap have also been installed on vault.