

**Operator: CIVITAS NORTH LLC**  
**Location Name: Hunt 8-60 17B**  
**Loc ID: 457475**  
**Inspection: 696305977**





**Exhibit A**

**CA:** Day Tank Containment Netting in disrepair - need to cover whole opening. See photos. Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.

**CA Resolution:** Operator has appropriately repaired/installed Wildlife Netting at identified Day Tank to comply with Rule 902.b.