



99999999

**OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT**☒ NOTICE OF UNSATISFACTORY INSPECTION☐ NOTICE OF SATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801

Denver, CO 80203

(303)894-2100

API No. 05-	121 - 07009	LEASE NAME:	Rediess 1		
LOCATION:	SESE 9-2N-54	OPERATOR:	Taylor		
DATE:	12-4-95	INSPECTOR:	Binkley		
Insp. Type: 5R	Insp. Status: PA	PA: Y <input checked="" type="radio"/> N <input checked="" type="radio"/>	Pass/Fail: P <input checked="" type="radio"/> F <input checked="" type="radio"/>	Viol. Y <input checked="" type="radio"/> N <input checked="" type="radio"/>	NOV: Y <input checked="" type="radio"/> N <input checked="" type="radio"/>

INSPECTION ITEM**COMMENTS****INPUT**

Well ID Signs (Rule 210)	w/ Ed Baster	
Pits (Reserve/Production) (Rule 902, 903, 904)		
Fences (Rule 604.C.(3), 1003.A)	Well plugged + capped	
Tank Battery Equipment (Rule 604)	Cement pump base	
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)	grass land	
Miscellaneous	40 Ed Baster - not a significant problem.	



00064989

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site