

Interim and Stormwater Inspection

February 12, 2024

Operator: GMT Exploration Company LLC - #10243

Location ID: 479197

Inspection Document #: 709400809

Elbert County, CO

NESW Section 24 T6S R65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Marble-Redstone pad
Facility ID: 479197



Photo 1. Photo taken of location sign.



Photo 2. Photo taken of wellhead on site. Photo taken facing northeast.



Inspection Photos
Location Name: Marble-Redstone pad
Facility ID: 479197



Photo 3. Photo taken of tank battery on site. Photo taken facing west.



Photo 4. Photo taken of vegetation and weeds (russian thistle & kochia) on topsoil stockpile in interim reclaimed area of well pad. Photo taken facing southeast.



Inspection Photos
Location Name: Marble-Redstone pad
Facility ID: 479197

Feb 12, 2024 at 12:57:10 PM
Parker CO 80138
United States



Photo 5. Photo taken of vegetation and weeds (russian thistle & kochia) along access road to pad, on the west of well pad. Photo taken facing north.

Feb 12, 2024 at 12:57:22 PM
Parker CO 80138
United States



Photo 6. Photo taken of vegetation and weeds (russian thistle & kochia) along access road to pad, on the west of well pad. Photo taken facing south.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400809

Inspection Photos

Location Name: Marble-Redstone pad

Facility ID: 479197



Photo 7. Photo of weeds (russian thistle & kochia) on top soil stockpile of site. Photo taken facing east.



Photo 8. Photo of weeds (russian thistle & kochia) on the east side of pad. Photo taken facing south.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400809

Inspection Photos
Location Name: Marble-Redstone pad
Facility ID: 479197



Photo 9. Photo of vegetation and weeds (russian thistle & kochia) on top soil stockpile of site. Photo taken facing east.



Photo 10. Photo of unstacked wattles at toe of the slope in perimeter ditch on west side of site . Photo taken facing west.

Inspection Photos

Location Name: Marble-Redstone pad

Facility ID: 479197



Feb 12, 2024 at 1:03:29 PM
Parker CO 80138
United States



Feb 12, 2024 at 1:04:41 PM
Parker CO 80138
United States

Photo 11. Photo of stormwater erosion/reeling on north side of pad. Photo taken facing south.

Photo 12. Photo of unused equipment and weeds on site. Photo taken facing east.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400809

Inspection Photos

Location Name: Marble-Redstone pad

Facility ID: 479197



Photo 13. Photo of trash on site. Photo taken facing east.



Photo 14. Photo of reeling on fill slope of pad on the north side of pad. Photo taken facing north.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400809