

Inspection Photos
Location Name: Elmer 8-31H
Location ID: 305202



Energy and Carbon Management Commission
40.95966, -104.36115, 5324.6ft
02/28/2024 11:39:43



Energy and Carbon Management Commission
40.95972, -104.36065, 5299.8ft
02/28/2024 11:39:03

Photo 1 – Tank Battery Sign

Photo 2 – Tank Battery

Inspection Photos
Location Name: Elmer 8-31H
Location ID: 305202



Energy and Carbon Management Commission
40.9597, -104.36081, 5311.3ft
02/28/2024 11:39:15



Energy and Carbon Management Commission
40.95964, -104.36127, 5316.4ft
02/28/2024 11:39:54

Photo 3 – Container Labels

Photo 4 – Heater Treater

Inspection Photos
Location Name: Elmer 8-31H
Location ID: 305202



Photo 5 – Flare and ECD

Photo 6 – Pumping Unit

Inspection Photos
Location Name: Elmer 8-31H
Location ID: 305202



Photo 7 – Well Sign

Photo 8 – Wellhead

Inspection Photos
Location Name: Elmer 8-31H
Location ID: 305202



Photo 9 – Risers marked



Photo 10 – Heater Treater