

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, LINDAUER-68S96W/3SWSE

Location ID: 334105

Date: 2/26/2024



Location Entrance – Photo #09586



Wellheads – Photo #09588

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, LINDAUER-68S96W/3SWSE

Location ID: 334105

Date: 2/26/2024



Separators – Photo #09589



Tank Battery – Photo #09590



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, LINDAUER-68S96W/3SWSE

Location ID: 334105

Date: 2/26/2024



**Lack of Stabilization – Photo #09587**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #09592**