

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/21/2024

Submitted Date:

02/22/2024

Document Number:

707602428**FIELD INSPECTION FORM**

Loc ID 331950	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 14 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>100322</u> Name of Operator: <u>NOBLE ENERGY INC</u> Address: <u>2001 16TH STREET SUITE 900</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE				

Contact Information:			
Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
331950	LOCATION	AC			-	SCHMIER-65N64W 32SWSW	IO

General Comment:

This is a BATTERY inspection.
 Well(s): 2: Temporarily Abandoned | TA.
 Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs
 (331950, 329183).
 (Well(s): 2: Temporarily Abandoned | TA).

Centralized Battery Formerly served 1 Location ID
 (329175).
 (Well(s): 1: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID
 (Pending).

Reference (Associated Well(s), Battery Inspections):
 A.) Field Inspection Report doc. #707602422 and/or Location ID #331950
 for TA Well(s) info.
 B.) Field Inspection Report doc. #707602424 and/or Location ID #329183
 for TA Well(s) info.
 C.) Field Inspection Report doc. #707602426 and/or Location ID #329175
 for PA Well(s) info.
 D.) Field Inspection Report doc. #707602428 and/or Location ID #331950
 for Battery / Facility, Equipment info.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:	OOSLAT applied at Battery equipment.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	NFPA placard missing at/on crude oil tank. Refer to Rule 605.h(1)E for guidance. See photo #6.			
Corrective Action:	*Post NFPA placard at/on crude oil tank. Comply with Rule 605.h(1)E. Corrective Action date: 03/25/2024. (30-days). See photo #6. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.			Date: 03/25/2024
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	IGNITOR/COMBUSTOR			
Comment:	Iron panel.			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Surrounded by metal berms.			
Corrective Action:				Date:
Equipment:				
Type: Emission Control Device		# 2	corrective date	
Comment:	1: Crude storage vapor line combustor(s). Controls crude oil tank(s) vapors. Pilots: OFF Shut-down. 1: Separator vapor line combustor(s). Controls separator(s) vapors. Pilots: OFF Shut-down.			
Corrective Action:				Date:

Type: Gas Meter Run	# 2	
Comment:	Gas Sales: Calibration card(s) indicates calibration > 1 year. (DCP). Last calibration: 03/03/2020. Inactive, NO production.	
Corrective Action:		Date:
Type: Bird Protectors	# 3	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment:	Battery site: 2: ECD scrubber(s).	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 2 Location IDs (331950, 329183). (Well(s): 2: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	48 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.351972,-104.582710
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	331950	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	IO

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On WED 02/21/2024 at approximately 16:40 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Facility Name: Pending Facility ID: Pending Location Name: SCHMIER-65N64W/32SWSW Location ID: 331950 Well Name(s): Schmier 19-32, HSR-Tullberg 13-32. API: 123-21618, 123-16976. Location County: Weld County, Colorado Weather: Mostly Cloudy, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned T.A. Battery: Inactive Shut-down.</p> <p>During this inspection the following possible compliance issue(s) were observed: 1.) NFPA placard missing at/on crude oil tank. Refer to Rule 605.h(1)E for guidance. *Post NFPA placard at/on crude oil tank. Comply with Rule 605.h(1)E. Corrective Action date: 03/25/2024. (30-days). See photo #6. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.</p> <p>*A follow up on this site inspection will be conducted to ensure that compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a synopsis of the inspection report.</p>	evinsb	02/22/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403695777	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6439206
707602429	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6439200