

Operator: Extraction Oil and Gas
Location Name: GREEN-61S68W 17SESE
Loc ID: 321507
Inspection: 697505089



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F

CA: This location does not comply with Rule 1004. The access road, well and tank battery location have mostly annual, weedy vegetation, which is not reflective of reference area vegetation. Also, there appears to be subsidence at the wellhead. There has been some land use change along a portion of the access road that is not the responsibility of the Operator. The surface owner has a fire pit that is being accessed via a portion of the access road. Operator is responsible for the red outlined area shown in Photo #4.

CA Resolution: This location has been reclaimed to comply with Rule 1004.