

WELL SITE INSPECTION FORM  
(DRILLING AND PLUGGING)

121-07050

Well Name Xenia 4-3  
Operator Kingwood  
Location SWNW12-2A54  
Field Xenia

API Number 05 - 121 -  
Permit #   
County Washington  
Inspector EBB



AL/PA/DA Inspection Results:

Well Status:

Pass(Y) X Fail(N)  Date 9-25-91 ND  DG  WO  PR  SI  TA

Date of Inspection Before/During Drilling

Surf. Csg. Size  Setting Depth  Cmt. Vol.  WOC time

Consistent with APD casing Program? YES  NO  Returns

Rig  BOP'S  Stage Tool Depth  Cmt. Vol.

Date of Inspection Before/During/After Completion

Prod. Csg. Set?  Completion Rig/Activity

Drilling Pits: Closed  Open  Wellhead Installed:  Sign: Yes  No

Tank ID: Yes  No  N/A  Skim Tank/Pit:  Prod. Tanks: ( )  BBLs

Equipment  Meter Run: Yes  No

Bradenhead Press:  Fluid: No  Yes  Type  Well Cat.

AL/PA/DA Inspection

Date Plugged: 9-15-66

Date Permit Expired:

Hole Plugged: Yes  No

Pits Backfilled: Yes  No

Material Buried: Yes  No  N/A

Site Clean: Yes  No

Bond Release OK: Yes  No  Fed

Hole Marker: Yes  No

Date of Safety/Status Inspection

Comments:



00599680

Violations: Yes  No  Notice Sent: Yes  No  Date Sent: