

Final Reclamation Inspection

February 22nd, 2024

Operator: Logos Operating LLC - 10679

Location ID: 333513

Inspection Document #: 714000484

La Plata County, CO

Township: SESE 8 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bondad 33-9 32
Location ID: 333513



Photo 1. View of the disturbance facing center from the entrance.



API #: 067-05470



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Bondad 33-9 32
Location ID: 333513



Photo 2. View of rill erosion that persists on the southern edge of the disturbance and within the western interim reclamation area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-05470

Inspection Photos
Location Name: Bondad 33-9 32
Location ID: 333513



Photo 3. View of woody debris observed on the location.



Inspection Photos
Location Name: Bondad 33-9 32
Location ID: 333513

2/22/24
+37.114558,-107.843649
286° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of reference area comprised of sagebrush.

API #: 067-05470