



**COLORADO OIL & GAS CONSERVATION COMMISSION**  
**FIELD INSPECTION REPORT**



<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		Denver, CO 80203	
		(303)894-2100	
API No. 05- <i>124 - 07075</i>		LEASE NAME: <i>Minkler-Xenia 4-1X</i>	
LOCATION: <i>NENWNE 11-2N-54</i>		OPERATOR: <i>Kingwood-Xenia Unit, ?</i>	
DATE: <i>3-6-97</i>		INSPECTOR: <i>EBB</i>	
Insp. Type: <i>HR</i>	Insp. Status: <i>PA</i>	PA: Y <input type="radio"/> N <input checked="" type="radio"/>	Pass/Fail: P <input type="radio"/> F <input checked="" type="radio"/>
		Viol. Y <input type="radio"/> N <input checked="" type="radio"/>	NOV: Y <input type="radio"/> N <input checked="" type="radio"/>

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210, 604.c(4))	<i>3" flow line, old oily soil</i>	
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)	<i>cement cistern? with <i>free</i></i>	
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)	<i>oil underground.</i>	
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)	<i>due N of present battery</i>	
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)	<i>1/2 mile, <i>(1X Xenia)</i></i>	
<b>General Housekeeping</b> (Rule 603)	<i>20' old pit with grass cover</i>	
<b>Spills (Oil/Water)</b> (Rule 907)	<i>oily dirt, misc junk.</i>	
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)		
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)		
<b>Miscellaneous</b>		

<b>CORRECTIVE ACTION REQUIRED:</b> <i>Remove junk, cement tank, rehab oily dirt, contour + reseed + crimp straw.</i>	
Date Corrective Action Required By:	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

