

Inspection Photos

2/27/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335773

Inspection Doc: 696205635

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335773



Photo 1: Photos taken from the north end of the Location, facing south and southwest.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335773



Photo 2: Working pad surface and Location entrance lacks stabilization. BMPs to stabilize the working pad surface remain missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335773



Photo 3: Photo taken from the interim areas west of the Location. Photos examples showing BMPs to manage runoff in a manner that minimizes erosion and degradation remain missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335773



Photo 4: See comments under photo 4.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335773



Photo 5: Lines at tank has been capped.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335773



Photo 6: Photo taken from the interim areas on the southwest end of the Location. Photos show wattle debris remains on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources