

Inspection Photos

2/27/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335424

Inspection Doc: 696205641

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335424



Photo 1: BMPs on the working pad surface have not been maintained; Working pad surface lacks stabilization and tracking BMPs



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335424



Photo 2: Lines at tank has been capped.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 3: Anchors have not identified by a marker of bright color not less than four (4) feet in height.

