

Inspection Photos
Location Name: EHRLICH-66N64W/7NWSW
Location #: 322987




Photo #1

Ehrlich #1 (123-12382) Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: cmt-surf



Photo #2

Ehrlich #1 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: cmt-surf
*Site safety signage
prior photo*



Inspection Photos

Location Name: EHRlich-66N64W/7NWSW
Location #: 322987



Photo #3
Ehrlich #1 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: cmt-surf
Wellsite entrance
prior photo




Photo #4
Ehrlich #1 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: cmt-surf
JSA: 2024-02-29



Inspection Photos

Location Name: EHRLICH-66N64W/7NWSW

Location #: 322987



Photo #5

Ehrlich #1 Battery site

Plugged & Abandoned | PA

Plugging Ops; Cementing: cmt-surf

Battery sign

prior photo



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources