



00048450

WELL SITE INSPECTION FORM
(DRILLING AND PLUGGING)

c

Well Name Huey 1-32x API Number 05 - 087 - 7984
 Operator Petex Permit # _____
 Location SWNW32-2N56 County Marion
 Field _____ Inspector EBBuddy

AL/PA/DA Inspection Results:

Well Status:

Pass(Y) ☒ Fail(N) _____ Date 10/29/91 ND _____ DG _____ WO _____ PR _____ SI _____ TA _____

=====

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
 Consistent with APD casing Program? YES _____ NO _____ Returns _____
 Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
 Drilling Pits: Closed _____ Open _____ Wellhead Installed: _____ Sign: Yes _____ No _____
 Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
 Equipment _____ Meter Run: Yes _____ No _____
 Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: _____ Date Permit Expired: _____
 Hole Plugged: Yes ☒ No _____ Pits Backfilled: Yes ☒ No _____
 Material Buried: Yes ☒ No _____ N/A _____ Site Clean: Yes ☒ No _____
 Bond Release OK: Yes ☒ No _____ Fed _____ Hole Marker: Yes _____ No _____

Date of Safety/Status Inspection _____

Comments: H&R finished cleanup for Bond Release

Violations: Yes _____ No _____ Notice Sent: Yes _____ No _____ Date Sent: _____

Jeannie - pl.
send this
request to
Gear only. Thanks.

8-26-91

John S.

I attempted to call Mr. Huey with no luck.
The Huey site has only 2 pieces of
equipment left on site, otherwise it
appears ok to release the bond.

EBB

↓ Last msg rd 8/20/91 showed
equipment still on site.
This was our
3rd inspection
for bond
release

Note: We will not release
this bond until:

1. Photos showing
restoration is
complete are
supplied
2. we make last inspection
3. Petex or H&R rep.
accompanies us to sight.

OK 8/26/91