

Inspection Photos
Location Name: Guthrie 2
Location ID: 320188



Photo 1 Entrance to location



Photo 2 Location pic

Inspection Photos
Location Name: Guthrie 2
Location ID: 320188



Photo 3 Ruts in road



Photo 4 Ruts off location

Inspection Photos
Location Name: Guthrie 2
Location ID: 320188



Photo 5 Stained Soil



Photo 6 More ruts off location

Inspection Photos
Location Name: Guthrie 2
Location ID: 320188



Photo 7 Ruts



Photo 8 No tracking pad

Inspection Photos
Location Name: Guthrie 2
Location ID: 320188



Photo 9 More ruts across road



Photo 10 No tracking pad

Inspection Photos
Location Name: Guthrie 2
Location ID: 320188



Photo 11 Separator



Photo 12 Vault with fluid open lid no marker sign

Inspection Photos
Location Name: Guthrie 2
Location ID: 320188

