

Inspection Photos
Location Name: Barnard 4-23
Location ID: 330172



Photo 1: Signage

Photo 2: Gas meter, riser

Inspection Photos
Location Name: Barnard 4-23
Location ID: 330172



Photo 3: Damaged fencing, no signage

Photo 4: Damaged fencing, no signage

Inspection Photos
Location Name: Barnard 4-23
Location ID: 330172



Photo 5: Damaged fencing, no signage