


KT Resources LLC
 WRS Unit 29-23
 Location ID: 316221



As signs are replaced additional information is required

Calibration overdue

**KT Resources LLC
WRS Unit 29-23
Location ID: 316221**




Rain cap missing



Open to wildlife

KT Resources LLC
WRS Unit 29-23
Location ID: 316221



As signs are replaced additional information is required



Debris

**KT Resources LLC
WRS Unit 29-23
Location ID: 316221**



Location from Northeast corner



Location from Southeast corner

**KT Resources LLC
WRS Unit 29-23
Location ID: 316221**



Location from Southwest corner



Location from Northwest corner