

# Final Reclamation Inspection

March 6th, 2024

Operator: Logos Operating LLC - 10679

Location ID: 326593

Inspection Document #: 714000508

La Plata County, CO

Township: NWNE 11 33N 10W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Bondad 33-10 5A  
Location ID: 326593



Photo 1. View of the disturbance facing center from the entrance.



API #: 067-08365



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos

Location Name: Bondad 33-10 5A

Location ID: 326593



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of the southern interim reclamation area facing south east.

API #: 067-08365



Inspection Photos

Location Name: Bondad 33-10 5A

Location ID: 326593



**Photo 3.** Woody stake debris observed on location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-08365



# Inspection Photos

Location Name: Bondad 33-10 5A

Location ID: 326593



**Photo 4.** View of rill erosion forming in the southeast and northeast portions of the disturbance.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-08365



Inspection Photos  
Location Name: Bondad 33-10 5A  
Location ID: 326593



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Culvert outlet CA identified in the previous inspection doc  
#693904163 has been addressed/resolved.

API #: 067-08365



Inspection Photos  
Location Name: Bondad 33-10 5A  
Location ID: 326593



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 6.** View of reference area comprised of indian rice grass, rabbit brush, sagebrush and juniper.

API #: 067-08365