



Cleaned spill location outside of containment



Three sided bin with stained gravel, removed from inside containment.



Inside of containment after hydrovac cleaning.