

# Inspection Photos

3/06/2024

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 335263

**Inspection Doc:** 696205671

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335263



**Photo 1:** Photos 1-2 taken from the working pad surface. Photos examples showing Stormwater and erosion control BMPs remain missing or insufficient; working pad surface lacks stabilization; tracking and erosion degradation observed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335263



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335263



**Photo 3:** Photos taken from the access road. Photo right from the 10/20/2023 inspection. Photo left example showing erosion degradation along the access road has persisted.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335263



**Photo 4:** Photo taken from the spur road. Photo shows sediment deposition into vegetated areas due to erosion/runoff from the road. Runoff from the road is also resulting in sediment deposition onto the Clough #135



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335263



**Photo 5:** Erosion degradation has persisted along the access road and ditch.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335263



**Photo 6:** Photo example showing noxious weed establishment (Halogeton) observed along the access road.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335263



**Photo 7:** Photos examples showing trash debris observed on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources