

Final Reclamation Inspection

March 6th, 2024

Operator: Logos Operating LLC - 10679

Location ID: 312080

Inspection Document #: 714000517

La Plata County, CO

Township: SWNW 14 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bondad 33-10 20
Location ID: 312080



3/6/24
+37.105879,-107.908709
310° NW



Photo 1. View of the disturbance facing center from the entrance.

Inspection Photos
Location Name: Bondad 33-10 20
Location ID: 312080



3/6/24
+37.106413,-107.909062
249° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the northern interim reclamation area facing west.

API #: 067-07463

Inspection Photos

Location Name: Bondad 33-10 20

Location ID: 312080



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of unused oil and gas piping equipment observed on location.

Inspection Photos
Location Name: Bondad 33-10 20
Location ID: 312080



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area comprised of grama, crested wheatgrass and juniper.

API #: 067-07463