

Final Reclamation Inspection

February 29th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333535

Inspection Document #: 714000491

La Plata County, CO

Township: SENW 18 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bondad 33-9-N33N9W 18 SENW
Location ID: 333535



Photo 1. View of the disturbance facing center from the entrance.



Inspection Photos

Location Name: Bondad 33-9-N33N9W 18 SENW

Location ID: 333535

2/29/24

+37.106977,-107.871143

186° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of western interim reclamation area facing south.

API #: 067-07129

Inspection Photos

Location Name: Bondad 33-9-N33N9W 18 SENW

Location ID: 333535



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of deteriorating and illegible simcoe produced water sign/label.

API #: 067-07129

Inspection Photos

Location Name: Bondad 33-9-N33N9W 18 SENW

Location ID: 333535



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of impacted surface material observed at the Simcoe well head.

API #: 067-07129

Inspection Photos

Location Name: Bondad 33-9-N33N9W 18 SENW

Location ID: 333535



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Exhaust muffler impacted material CA identified in the previous inspection doc #702500056 has been addressed/resolved.

API #: 067-07129

Inspection Photos

Location Name: Bondad 33-9-N33N9W 18 SENW

Location ID: 333535



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Reference area comprised of smooth brome and juniper.

API #: 067-07129