

Operator: 8 North

Location Name: Darlene East 29-N Pad

Loc ID: 452153

Inspection: 696306069



Exhibit A



Exhibit B

CA: 400 BBL Produced Water Tank missing NFPA Label. Install sign to comply with Rule 605.h.

CA Resolution: Sign has been installed to comply with Rule 605.h.

CA: Condensate Valve at ECDs - Vault Lid Cover is open to Atmosphere. Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.

CA Resolution: Vault Lid Cover has been repaired and closed to comply with Rule 902.b.