

Final Reclamation and Stormwater Inspection

Date: 03/11/2024

Operator: BONANZA CREEK ENERGY OPERATING
COMPANY LLC - 8960

Location ID: 429652

Inspection Document #: 708200982

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Latham 21-1 Pad
Location ID: 429652



Photo 1. Facing east towards the former access road. Culverts appear to have been removed and the access road has been recontoured. Gas gathering lines pictures left and right in photo.

Inspection Photos
Location Name: Latham 21-1 Pad
Location ID: 429652



Photo 2. Taken from the northwest corner of the location. The well location (Location ID 429652 with API 123-35857) meets final reclamation regulations and standards. Unable to find evidence of oil and gas activities and/or disturbances. Well location and access road appear reflective of the adjacent reference areas.

Inspection Photos
Location Name: Latham 21-1 Pad
Location ID: 429652



Photo 3. Taken from the northeast corner of the location; see comments in Photo 2.

Inspection Photos
Location Name: Latham 21-1 Pad
Location ID: 429652



Photo 4. Taken from the southeast corner of the location; see comments in Photo 2.

Inspection Photos
Location Name: Latham 21-1 Pad
Location ID: 429652



Photo 5. Taken from the southwest corner of the location; see comments in Photo 2.

Inspection Photos
Location Name: Latham 21-1 Pad
Location ID: 429652



Photo 6. Reference area photo taken south of the former location.