

Inspection Photos

Loc: 309302

Operator: OGRIS OPERATING LLC

Inspection Date: 3/13/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the wellsite. The fence around the pit is in disrepair.

