

Inspection Photos

Location Name: LARAMIE ENERGY LLC, NVega/2C Pad


Location ID: 334464

Date: 3/12/2024



Mar 12, 2024 at 11:49:44

Location Entrance – Photo #09820



Mar 12, 2024 at 11:51:27

Wellhead – Photo #09821

Inspection Photos

Location Name: LARAMIE ENERGY LLC, NVega/2C Pad

Location ID: 334464

Date: 3/12/2024



Separators – Photo #09823



Tank Battery – Photo #09824

Inspection Photos

Location Name: LARAMIE ENERGY LLC, NVega/2C Pad

Location ID: 334464

Date: 3/12/2024



Lack of Stabilization – Photo #09825



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09827**