

Inspection Photos


Location Name: LARAMIE ENERGY LLC, NVega/1D Pad

Location ID: 334451

Date: 3/12/2024



Location Entrance – Photo #09875



Wellheads – Photo #09878

Inspection Photos

Location Name: LARAMIE ENERGY LLC, NVega/1D Pad

Location ID: 334451

Date: 3/12/2024



Separators – Photo #09877



Tank Battery – Photo #09876

Inspection Photos

Location Name: LARAMIE ENERGY LLC, NVega/1D Pad

Location ID: 334451

Date: 3/12/2024



Lack of Stabilization – Photo #09880



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09881**