

# Final Reclamation and Stormwater Inspection

Date: 3/11/24

Operator: Noble Energy Inc - 100322

Location ID: 330907

Inspection Document #: 713900437

Weld County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Scottdale #26-14  
Location ID: 330907



**Photo 1.** The photo was taken at the tank battery location facing North. The photo illustrates the tank battery remains active for another well.



**Photo 2.** The photo was taken at the tank battery location facing East. Refer to the comment for photo 1.



Inspection Photos  
Location Name: Scottdale #26-14  
Location ID: 330907



**Photo 3.** The photo was taken at the well location access road facing South. The photo illustrates the access road is dominated by Russian thistle, Cheatgrass and Crested wheatgrass.



**Photo 4.** The photo was taken at the well location facing Southwest. The photo illustrates the well location is dominated by Saltgrass and Crested wheatgrass.



Inspection Photos  
Location Name: Scottdale #26-14  
Location ID: 330907



**Photo 5.** The photo was taken at the well location facing Northwest. Refer to the comment for photo 4.



**Photo 6.** The photo was taken at the well location facing Northeast. Refer to the comment for photo 4.



Inspection Photos  
Location Name: Scottdale #26-14  
Location ID: 330907



**Photo 7.** The reference photo was taken near the well location facing Northeast. The photo illustrates that reference areas are dominated by Saltgrass, Sand dropseed, Cheatgrass and Crested wheatgrass.