

# Final Reclamation and Stormwater Inspection

March 4, 2024

Operator: Petro- Canada Resources Inc- #72085

Location ID: 311680

Inspection Document #: 709400865

Adams County, CO

SESW Section 13 T3S R59W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: UPRR Noonan 1-B  
Location ID: 311680



**Photo 1.** Photo taken facing west of reclaimed access road.



**Photo 2.** Photo taken facing west of reclaimed access road.

Inspection Photos  
Location Name: UPRR Noonan 1-B  
Location ID: 311680



**Photo 3.** Photo taken facing west of reclaimed access road and weed debris in the fence.



**Photo 4.** Photo taken facing south of pad reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.

Inspection Photos  
Location Name: UPRR Noonan 1-B  
Location ID: 311680



**Photo 5.** Photo taken facing southeast of pad reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.




**Photo 6.** Photo taken facing east of reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.

## Inspection Photos

Location Name: UPRR Noonan 1-B

Location ID: 311680



**Photo 7.** Photo taken facing southwest of pad reclamation area of vegetation, weeds (russian thistle & kochia) and bare soil. Weeds indicated by yellow arrow, bare soil indicated by red arrow.

**Photo 8.** Closer view of bare area, Photo taken facing southwest of pad reclamation area of vegetation, weeds (russian thistle & kochia) and bare soil. Weeds indicated by yellow arrow, bare soil indicated by red arrow.



Inspection Photos

Location Name: UPRR Noonan 1-B

Location ID: 311680



**Photo 9.** Photo taken facing northeast of pad reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.


**Photo 10.** Photo taken facing east of reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.



Inspection Photos  
Location Name: UPRR Noonan 1-B  
Location ID: 311680



**Photo 11.** Photo taken facing north of pad reclamation area of vegetation and weeds (russian thistle & cheatgrass) and bare soil. Weeds indicated by yellow arrow, bare soil indicated by red arrow.



**Photo 12.** Photo taken facing northwest of pad reclamation area of vegetation and weeds (cheatgrass) and stormwater erosion of soil. Weeds indicated by yellow arrow, soil erosion indicated by green arrow.

Inspection Photos  
Location Name: UPRR Noonan 1-B  
Location ID: 311680



**Photo 13.** Photo taken facing southwest of native vegetation for reference.

Inspection Photos

Location Name: UPRR Noonan 1-B

Location ID: 311680



**Photo 14.** Photo taken facing south of rutted access road.

**Photo 15.** Photo taken facing northwest of rutted access road.

Inspection Photos

Location Name: UPRR Noonan 1-B

Location ID: 311680



Mar 4, 2024 at 12:07:44 PM  
Byers CO 80103  
United States



Mar 4, 2024 at 12:08:01 PM  
Byers CO 80103  
United States

**Photo 16.** Photo taken facing southwest of rutted access road with stormwater erosion.

**Photo 17.** Photo taken facing northwest of rutted access road with stormwater erosion.

