

# Interim Reclamation and Stormwater Inspection

March 11 , 2024

Operator: Wiepking Fullerton Energy LLC- #96340

Location ID: 420392

Inspection Document #: 709400907

Lincoln County, CO

SENW Section 20 T10S R55W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Bubba State #3  
Location ID: 420392



**Photo 1.** Photo taken of location sign.



**Photo 2.** Photo taken facing southeast of wellhead.



Inspection Photos  
Location Name: Bubba State #3  
Location ID: 420392



**Photo 3.** Photo taken facing north of staining around wellhead.



**Photo 4.** Photo taken facing southeast of staining around wellhead. yellow arrow indicates staining outside fenced area.



Inspection Photos  
Location Name: Bubba State #3  
Location ID: 420392



**Photo 5.** Photo taken facing northwest of secondary containment lacking wildlife protection.



**Photo 6.** Photo taken facing east of trash on site.



Inspection Photos  
Location Name: Bubba State #3  
Location ID: 420392



**Photo 7.** Photo taken facing east of vegetation in interim reclamation area.



**Photo 8.** Photo taken facing south of vegetation in interim reclamation area.



Inspection Photos  
Location Name: Bubba State #3  
Location ID: 420392



**Photo 9.** Photo taken facing south of tank battery sign



**Photo 10.** Photo taken facing southwest of tank battery.

