

Interim Reclamation and Stormwater Inspection

March 11 , 2024

Operator: Wiepking Fullerton Energy LLC- #96340

Location ID: 309632

Inspection Document #: 709400954

Lincoln County, CO

SWNE Section 6 T10S R55W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Kauai #2
Location ID: 309632




Photo 1. Photo taken of location sign.



Photo 2. Photo taken facing east of wellhead.



Inspection Photos
Location Name: Kauai #2
Location ID: 309632



Photo 3. Photo taken facing west of secondary containment without wildlife protection.



Photo 4. Photo taken facing north of secondary containment without wildlife protection.

Inspection Photos
Location Name: Kauai #2
Location ID: 309632



Photo 5. Photo taken facing east of vegetation in the interim reclamation area.



Photo 6. Photo taken facing east of vegetation in the interim reclamation area.

Inspection Photos
Location Name: Kauai #2
Location ID: 309632



Photo 7. Photo taken facing southeast of vegetation in the interim reclamation area.



Photo 8. Photo taken facing southeast of vegetation in the interim reclamation area.



Photo 11. Photo taken facing east of tank battery sign



Photo 12. Photo taken facing east of tank battery.

Inspection Photos
Location Name: Kauai #2
Location ID: 309632



Photo 11. Photo taken facing north of tank battery pad, weeds (kochia).



Photo 12. Photo taken facing west of tank battery pad, weeds (kochia).